

| | |
|---------------------------|-----|
| Figures | v |
| Tables | vi |
| Foreword | vii |
| Acknowledgments | ix |
| Units of Measurement | x |
| Introduction | i |
| Reservoir Characteristics | 2 |
| Reservoir Rock Types | 2 |
| Porosity | 4 |
| Permeability | 5 |
| Thickness | 7 |
| Saturation | 7 |
| Pressure and Temperature | 8 |
| Corrosive Fluids | 8 |
| To Summarize | 9 |
| Formation Evaluation | ii |
| Seismic Surveys | ii |
| Records from Nearby Wells | 12 |
| Driller's Logs | 12 |
| Mud Logs | 13 |
| Core Samples | 14 |
| Wireline Well Logs | 16 |
| Logging While Drilling | 23 |
| Formation Evaluation Data | 23 |
| To Summarize | 23 |
| Formation Testing | 25 |
| Wireline Formation Test | 26 |
| Drill Stem Test | 28 |
| Surface Well Tests | 34 |
| Usefulness of Test Data | 39 |
| To Summarize | 40 |
| Completion Design | 41 |
| Completion Methods | 41 |
| Flow Paths | 44 |
| Completion Systems | 46 |

Contents



| | |
|----------------------------|-----|
| Cost versus Potential | 51 |
| To Summarize | 52 |
| Completion Tools | 53 |
| Tubing | 53 |
| Production Packers | 55 |
| Seating or Landing Nipples | 60 |
| Flow Control Equipment | 60 |
| Erosion Control Equipment | 63 |
| Wellheads | 65 |
| Completion Procedures | 69 |
| To Summarize | 69 |
| Perforating | 71 |
| Jet Perforating | 72 |
| Stimulation | 76 |
| Running the Completion | 78 |
| To Summarize | 81 |
| Glossary | 83 |
| Review Questions | 103 |
| Answers | 111 |

| | | |
|-----|---|----|
| 1. | Sedimentary rock types, with standard symbols | 2 |
| 2. | Section from a seismic record | 12 |
| 3. | Section from a mud log | 13 |
| 4. | Removal of core | 14 |
| 5. | Sidewall coring gun operation | 15 |
| 6. | Wireline well logging | 16 |
| 7. | Spontaneous potential around the wellbore | 17 |
| 8. | Relationships of porosity, permeability, and resistivity | 19 |
| 9. | Removing a radioactive source from its carrier to load into a logging sonde | 20 |
| 10. | Schematic drawing of magnetic resonance tool | 21 |
| 11. | Well logging sonde | 22 |
| 12. | Wireline formation tester design | 26 |
| 13. | Drill stem test tool assemblies: a) tool assemblies, b) single-packer, c) straddle-packer | 28 |
| 14. | Typical pressure curve from a drill stem test | 32 |
| 15. | Microscope chart reader with computer | 33 |
| 16. | Surface well test components | 35 |
| 17. | Page from a typical well-test report | 37 |
| 18. | Open-hole completion | 42 |
| 19. | Perforated completion | 43 |
| 20. | Wire-wrapped screen liner | 43 |
| 21. | Conventional single-zone completion | 46 |
| 22. | Single-string dual completion: lower zone through tubing; upper zone through annulus | 47 |
| 23. | Single-string dual with Y-sub: upper zone through tubing | 48 |
| 24. | Parallel string completion | 49 |
| 25. | Miniaturized multiple completion | 50 |
| 26. | Running tubing into a well | 53 |
| 27. | Packing elements | 56 |
| 28. | Slips | 56 |
| 29. | Hold-down buttons | 57 |
| 30. | Drag blocks | 57 |
| 31. | Drag springs above slips and packing elements | 57 |
| 32. | Tension packer | 58 |
| 33. | Compression packer | 58 |
| 34. | Permanent packer | 59 |
| 35. | Seating nipple | 60 |

Figures



| | | |
|-----|--------------------------------|----|
| 36. | Sliding sleeve | 61 |
| 37. | Check valve | 61 |
| 38. | Subsurface safety valves | 62 |
| 39. | Flow coupling | 64 |
| 40. | Wellhead components | 65 |
| 41. | Two types of Christmas trees | 67 |
| 42. | Beam pumping unit | 68 |
| 43. | Jet perforating | 72 |
| 44. | Shaped perforating charge case | 73 |

Tables

| | | |
|----|---|---|
| 1. | Variations in porosity and permeability | 6 |
|----|---|---|

