Radiation/Contamination Survey Record

Date	Time	Instrument Model #	Instrument Serial #	Bkgd (dpm)	Survey Description (location of survey, items surveyed, etc.	Survey Results (dpm/100 cm^2)	Signature
01Apr05	0900	Ludlum 3	198712	50	Direct survey of MBB 3.101 north bench rad area near sink.	Nothing above background	Radiation Worker
01Apr05	1430	LS6500	707326	86	Smear samples of inside of Beckman centrifuge in WEL 4.265	See attached LSC printout	Super Technician